工程紀錄 JOB REFERENCE

斜坡、地盤平整、道路、渠務 及 園景工程 Slope, Site Formation, Road, Drainage and Landscaping Works

工程項目	工程性質	僱主	顧問
Description of Works	Scope of Works	Client	Consultants
Slope Remedial Works 12-14 Shouson Hill Road	Slope remedial & soil nailing	Bailey Engineering	
Site Formation Works at 64-64A Mount Davis Rd- IL 2348-49	Earth retaining structures and drainage	New House Construction Ltd.	
Proposed Residential Redevelopment at	Earth retaining	Wah Seng General	Canwest Consultants (Int'l)
43-45 Beacon Hill Road, Kowloon.	structures and drainage	Contractors Ltd.	Limited
Proposed Lard Boiling Factory in Industrial	Earth retaining	Sui Kwan	Michael W.K. Yuen
(Group D) Zone, Government Land in DD 107, Fung Kat Heung, Yuen Long	structures and drainage	Construction Ltd.	
Proposed Residential Development at RBL	Earth retaining	Konwall	
No. 589 & 590, No. 37 Severn Road, The Peak	structures	Construction Engineering Co. Ltd.	
Lot No. 2596, DD92, Hang Tau Road, Sheung Shui	Earth retaining structures and drainage	Wah Seng General Contractors Ltd.	Ove Arup & Partners Hong Kong Ltd.
Redevelopment at No. 3 South Bay Road	300 nos. rock dowels	New House Construction Co. Ltd.	Canwest Consultants (Int'l) Limited
Slope Upgrading Works at The South of Lot 53 R.P. in D.D. 175, Hung Kiu Lane, Kau To, Sha Tin	Slope Upgrading	E. Life Property Mgt Ltd.	M2 Engineering Ltd.
A & A at 33 Consort Rise, Hong Kong (Culture Homes at The Kellett)	Slope improvement	Yearfull Contracting Limited	
Contract C119 - Bermuda Triangle Concrete Paving Base and Seating Wall, Ocean Park	Landscaped Works	Ocean Park	Ocean Park
Ocean Park - Civil Works for facilitating	Roadworks, slope	Ocean Park	Ocean Park

HEC's 22KV cable laying from Tai Shue	and aarth rataining		
Wan to Vet Centre & Marine World via	and earth retaining structures		
Panorama Road	structures		
Retaining Wall Stabilzation Works,	DH Order	Tribuild	Tom Leung Consulting
Retaining wall Feature No. 7SW-D/R104,	DII Oldei	Engineering Ltd.	Engineers, Professional
Block 11, On Ting Terrace, No. 1 Hang Lok		Eligineering Ltd.	Geotechnical Consultant
Lane, Tung Lo Wan, Tai Wai, Shatin			Geoteeninear Consultant
Development of Residential Building at 16	Retaining Wall and	New House	Kenneth K.C. Chan &
& 18 Bonham Road, HK	Slope Formation	Construction Ltd.	Associates
Development of Residential Building at 16	Site Formation	Queen Cheers	Kwong & Associates Ltd.
& 18 Bonham Road, HK	Specialist Specialist	Development Development	Kwong & Associates Ltd.
& 18 Bolliani Road, 11K	Contractor	Development	
Installation of dia. 750 mm storm water	Underground	Ocean Park	Design and Build Contract
drain at AC Play Zone, Ocean Park	Drainage	Ocean Faik	Design and Bund Contract
		Hong Vona	David S.K. Au & Associates
Slope Remedial Works for Feature No. 3SE-C/C80	Slope Remedial	Hong Kong Institute of	
3SE-C/C80		Education	Ltd.
		Education	
Charles And Addition			
(中国区、1786年))			
A second			
Roadmarking, Ocean Park	Roadwork	Ocean Park	
Feature No. 14NE-B/C12 Adjoining 29	Slope Repairs	Mr. Sydnes S.L.	Wadabuild
Yung Shue Long New Village, Lamma		Wan	(design & build)
Island			-
A CONTRACTOR OF THE PARTY OF TH			
06)11701			
Design & Build a Disable Ramp along	Building Addition	Ocean Park	Wadabuild
existing staircase bridging Aqua City and	& Alteration		
SkyFair			
Installation of a Dia. 750mm Storm Water	Drainage and	Ocean Park	Wadabuild
drain at AC Play Zone, Ocean Park	Roadwork		(design & build)
	AND THE RESERVE OF THE PERSON		
	AND "		
	1		
	the state of the s		
Class Harris I'm W. 1. C. T N	C1 II "	Clima	Add Cold Total
Slope Upgrading Works for Feature Nos.	Slope Upgrading	Chinese Permanent	Atkins China Ltd.
11SE-D/C99, C100, CR526, CR485 and	Works	Cemetery	
Unregistered Features at Northern end of			
C100 and Southern end of CR485 at Cape			
Collinson			

Proposed Open Staircase at Terrace 1 of	Slope Upgrading	Chinese Permanent	Spence Robinson
Section 35 Chinese Permanent Cemetery,	Works / Foundation	Cemetery	
Cape Collinson Road, Hong Kong - I.L. 7715 R.P.	/ Superstructure		
Slope & Retaining Structure Upgrading Works for Feature Nos. 11SE-D/CR538at Cape Collinson at Chinese Permanent Cemeteries	Slope Upgrading Works	Chinese Permanent Cemetery	Atkins China Ltd.
Silt Screen Gabion Wall at Pools, Tai Shue	Gabion Wall	Ocean Park	
Wan, Ocean Park	Construction		
Upgrading Works for Slope & Retaining Walls at	Slope and Retaining	Chinese Permanent	Atkins China Ltd.
Cape Collinson Chinese Permanent Cemetery Lot No. IL7715 P.R. & Ext.	Wall Remedial Work	Cemetery	
Slope and Retaining Wall Maintenance Works at	Slope and Retaining	IO of Craigmount	Percy Thomas Partnership
Craigmount, 34 Stubbs Road	Wall Remedial Work		(HK) Ltd.